

## **Product Change Notice**

Micron PCN: 31425 Date: 12/23/2014

Revision 1, 1/8/2015: This document supersedes original PCN#31425 dated 12/23/2014. Corrected part

number table to correctly display Suggested Replacement Part.

Type of Change:	End of Life	
Title of Change:	Automotive Serial NOR Flash MPNs (Marketing Part Numbers) Termination	
Description of Change:	Multiple, Serial NOR Flash MPNs are going to be terminated due to low demand and to enable improved supply line efficiency and focus on Microns' commitment to NOR technology. Current limited production volumes don't justify the continued availability.	
Reason for Change:	Better Align With Industry Standard	
Contact Information:	Marketing Contact VINCENZO NICOTRA Micron Semiconductor Ital VNICOTRA@MICRON.COM	Engineering Contact GIOVANNI MESSINA Micron Semiconductor Ital GMESSINA@MICRON.COM

Product Affected: Multiple Serial NOR Flash

Affected Micron Part Number	Suggested Replacement Part
M25P64-VMF3TPB	N25Q064A13ESFA0F
M25P64-VMF6TPBA	N25Q064A13ESFH0F
M25P32-VMW6TGBA	N25Q032A13ESEH0F
M25P32-VMF3TPB	N25Q032A13ESFA0F
M25P32-VMW3TGB	N25Q032A13ESEA0F

**Micron Sites Affected:** Fab13 – MSA – Singapore

## **Product/Data Schedule**

## **Current/Discontinued Product:**

Last Purchase Date\*: 1-Jun-2015
Last Shipment Date: 31-Dec-2015

<sup>\*</sup>Orders placed prior to the last purchase date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.