

## **Global Change Notification (GCN)**

Product Family	.093 Wafercon PCB	10728956
		GCN Number
Series	1840	November 09, 2015
		Date Issued
Reason For Change	Obsolescence	
Change Description	This is to inform you that the part(s) referenced in this notice will be made obsolete due to low demand and worn tooling. Please contact your Molex Sales Engineer for additional questions concerning possible replacement part(s).	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception		
Assessment Of Change (How Product Will Be Qualified & Validated)	Not applicable	
Internal Molex Qualification Date (Planned Date Information Available)		
Sample Availability Date (Changed Part)		
Date of Implementation	November 10, 2016	
Method of Identifying Change	Not applicable	
Recommended Replacement Parts	No replacement parts available.	
Last Time Buy Date for Obsolete Parts	August 15, 2016	
Last Time Ship Date for Obsolete Parts	September 28, 2016	

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com