**Light is OSRAM** 



15.06.2016

## OS-IN-2016-014

# Introduction of new carrier tape for PointLED (reverse mount devices according to data sheet)

Objective	Introduction of new carrier tape for PointLED reverse mount devices
	PointLED (reverse mount devices according to data sheet):
Products affected	LA P476, LA P47B, LA P47F, LB P4SG, LCB P473, LG P47K, LO P476, LO P47F, LO P47K, LP P47F, LR P47F, LS P47F, LS P47K, LS P476, LT P4SG, LT PWSG, LW P473, LW P4SG, LY P476, LY P47B, LY P47K, LY P47F

### **Background**

Capacity extension of carrier tape production for PointLED

#### **Current status**

Top view



Bottom view

Side view






New status

Top view

Bottom view

Side view





**Time Schedule** 

Start of delivery of CW 27/2016 (Both versions are used in production)

OS-IN-2016-014 15.06.2016

#### **Assessment**

No change in fit, form, function and reliability of LED. No change in carrier tape specification according to datasheet.

Please direct your inquiry to your local Sales office.

OSRAM Opto Semiconductors GmbH

Head Office:

Leibnizstrasse 4
93055 Regensburg, Germany
Phone +49 941 850-5
Fax +49 941 850-1002
www.osram-os.com

