

Not For New Design OS-NFND-2022-011

03 October 2022

Expected discontinuation date:	2/1/2023
---------------------------------------	----------

Reason:


OSRAM OS Expectations:

The following products have reached their end of life.

Please use our recommended replacement for new designs. If they may not fit, please contact your local sales office for other solutions.

Additionally we ask you to switch for running project as soon as possible to the proposed replacement. Anyway please check your demand and feedback your requested lifetime of these products.

Attention: Q# already announced to be in phase-out process will not be impacted. Dates published in corresponding PDN will be kept.



Please direct your feedback to your local Sales office.

Expected discontinuation date:	2/1/2023
---------------------------------------	----------

Reason: The following products have reached their end of life.

Not for new design products				Recommended Replacement		
Device	Ordering Code	Brand	Expected PDN start	Device	Datasheet Ordering Code	Brand
SU CZHPF1.VC	Q65113A2924	OSLON® UV 6060	2/1/2023	SU CZHEF1.VC	Q65113A4719	OSLON® UV 6060
SU CZHPF1.VC	Q65113A2937	OSLON® UV 6060	2/1/2023	SU CZHEF1.VC	Q65113A4719	OSLON® UV 6060
SU CZHPF1.VC	Q65113A4085	OSLON® UV 6060	2/1/2023	SU CZHEF1.VC	Q65113A4719	OSLON® UV 6060

Ordering Code Notification	Device	Product Descr.	Brand	Exp. PDN Date	Repl. Product Descr.	Repl. Ordering Code
Q65113A2924 OS-NFND-2022-011	SU CZHPPF1.VC	SU CZHPPF1.VC-U1U4-L1L2-V1-250-R18	OSLON	2/1/2023	SU CZHEF1.VC-U1U2-L0-V2-250-R18	Q65113A4719
Q65113A2937 OS-NFND-2022-011	SU CZHPPF1.VC	SU CZHPPF1.VC-U1U4-L1L2-V1-250-R18B	OSLON	2/1/2023	SU CZHEF1.VC-U1U2-L0-V2-250-R18	Q65113A4719
Q65113A4085 OS-NFND-2022-011	SU CZHPPF1.VC	SU CZHPPF1.VC-U1U4-L1-V1-250-R18B-GF	OSLON	2/1/2023	SU CZHEF1.VC-U1U2-L0-V2-250-R18	Q65113A4719