

Global Change Notification (GCN)

Product Family	.093 Pin and Socket Plug Housing	10649998	
		GCN Number	
Series	42191	August 21, 2014	
		Date Issued	
Reason For Change	Obsolescence		
Change Description	The molds used to make housing series 42191 are worn beyond repair and are no longer able to make acceptable product.		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to	e-mail message.	
Reason For Short Notice Exception	Force Majeure		
Assessment Of Change (How Product Will Be Qualified & Validated)			
Internal Molex Qualification Date (Planned Date Information Available)			
Sample Availability Date (Changed Part)			
Date of Implementation	August 31, 2014		
Method of Identifying Change	Not Applicable		
Recommended Replacement Parts	Not Applicable		
Last Time Buy Date for Obsolete Parts	August 31, 2014		
Last Time Ship Date for Obsolete Parts	August 31, 2014		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com