



Product Change Notification

TE Connectivity

Product Change Notification: P-18-015314

PCN Date: 11-JAN-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Obsolete AMP-DUAC (Part 3)

Description of Changes

Dear Customers, TE Connectivity is ending the AMP-DUAC product family. We apologize for any inconveniences this may cause but many AMP-DUAC offerings have VAL-U-LOK equivalents. [AMP-DUAC = VAL-U-LOK], [794576 = 794955], [794576 = 794955], [794577 = 1586314], [794578 = 794957], [794579 = 1586316].

Reason for Changes:

Part status change.Document clarification.Same as E-17-010621:Obsolete AMP-DUAC(part3), only modify the date as below: 1.modify Estimated Last Order Date For Obsolete Parts from Nov 1, 2019 to Mar 18,2018 2.modify Estimated Last Ship Date For Obsolete Parts from Dec 31, 2019 to Apr 2,2018

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
794577-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
794577-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
794577-1	NO						