

12500 TI Boulevard, MS 8640, Dallas, Texas 75243

PCN# 20150619003 Datasheet update for BQ25504 Information Only

 Date:
 7/1/2015

 To:
 Digi-Key PCN

Dear Customer:

This is an information-only announcement of a change to a device that is currently offered by Texas Instruments.

The changes discussed within this PCN are for your information only.

Any negotiated alternative change requirements will be provided via the customer's defined process. Customers with previously negotiated, special requirements will be handled separately. Any inquiries should be directed to your local Field Sales Representative.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (<u>PCN ww admin team@list.ti.com</u>).

Sincerely,

PCN Team SC Business Services

20150619003 Information Only Attachments

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE

BQ25504RGTT

CUSTOMER PART NUMBER

null

Technical details of this Product Change follow on the next page(s).

PCN Number:	CN Number: 20150619003 PCN Date: 07/01/2015							/2015	
Title: Datasheet update for BQ25504									
Customer Contact:	PCN Manager		D	Dept:		Quality Services		vices	
Change Type:									
Assembly Site		Design			Wafer	Bum	p Site		
Assembly Process		Data Sheet				Bump Material			
Assembly Material		Part number change				Bump Process			
Mechanical Specif	ication	Test Site			Wafer	· Fab Site			
Packing/Shipping/	'Labeling	Test Process			Wafer	- Fab Materials			
Wafer Fab Process									
PCN Details									
Description of Change:									
Texas Instruments Incorporated is announcing an information only notification.									
The product datasheet(s) is updated as seen in the change revision history below:									
						ψŢ	XAS		
bq25504							STRUME	NTS	
SLUSAHOC-OCTOBER 2011-REVIS	ED JUNE 2015						www.ti.	.com	
Changes from Revision B (December 2014) to Revision C					P	age			
Changed the Test Condition for P _{IN(CS)} in the <i>Electrical Characteristics</i>									
 Changed the values for PIN(CS) in the Electrical Characteristics From: TYP = 10, MAX = 50 To: TYP = 15, MAX 									
deleted									
Changed C _{FLTR} To: C _{BYP} Figure 14									
Changed CBYP = 0.1 µF To: CBYP = 0.01 µF in <i>Detailed Design Procedure</i> 18 Changed C									
Changed C _{FLTR} To: C _{BYP} in Figure 21									
 Changed CBYP = 0.1 μF To: CBYP = 0.01 μF in <i>Detailed Design Procedure</i>									
 Changed CBYP = 0.1 µF To: CBYP = 0.01 µF in <i>Detailed Design Procedure</i>									
								20	
The datasheet number	will be changing								
Device Family		Change From:							
BQ25504		SLUSAH0B			SLUSAHOC				
Those changes may be	roviowed at the	datasheet links provided							
http://www.ti.com/pro		uatasheet links provided	•						
<u>neep.// www.en.com/pro</u>	<u>uuci bqz3304</u>								
Reason for Change:									
To more accurately ref	lect device chara	cteristics.							
		nction, Quality or Relia	abili	ity	(posi	tive	/ nega	tive):	
		ation change announcem		_			-		
Changes to product identification resulting from this PCN:									
None.									
Product Affected:									
BQ25504RGTR		BQ25504RGTT							
		= 12000							

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com