

## Product/Process Change Notifications



# PCN - 16 070

Release Date: August 09 2016

<b>Product Name:</b>	ExaMAX		
	6 pair right angle receptacle and right angle header		
<b>Product Manager:</b>	David Jiang		
<b>Subject:</b>	Notification of Planned Change		
<b>Distribution:</b>	Global		
<b>Type of Change:</b>	Design Change		
<b>Change Description:</b>	Ground hole location now rotate 90 degree(see attached picture)		
<b>Reason for Change:</b>	Automatic assembly process improvement result in 90 Degree change in the locating hole in ground shield plate.This change has no effect on the function and application		
<b>Affected Parts:</b>	refer to attachment		
<b>Effective Date of Change:</b>	November 25, 2016		
<b>Last Time Buy Date:</b>	NA		
<b>Last Disty Return Date:</b>	NA		
<b>Last Time Shipment Date</b>	NA		
<b>Datasheet Attached?</b>	No		
<b>Qual/Test Data Attached?</b>	No		
<b>Samples Availability Date:</b>	October	01	2016
<b>Available Alternatives?</b>	Select		
<b>Questions?</b>	<i>Contact your local AFCI Representative, or Product Manager</i>		
	<i>David Jiang/Product Manager</i>		
	<i>12242486736 David.Jiang@FCI.com</i>		

**Note:**

Customers should contact Product Manager (or their local AFCI Representative) directly regarding any concern on the PCN. Lack of any such customer feedback within three weeks of PCN release date will be interpreted as non-objection .