



April 30, 2021

Cinch Authorized Distributors:

Due to manufacturing issues, effective immediately, the below part numbers are discontinued. Unfortunately, we cannot offer an alternative or a last time buy. Please make the appropriate changes in your system. If you have any of the discontinued part numbers in your inventory and wish to return them, you have 30 days to request an RMA. The parts will need to be functional and purchased from Cinch Connectivity Solutions within the last two years.

The part number effected are:

50GP1      50GP1B

SDLB      SDLB06080      SDLB125

Cinch apologizes for any inconvenience this may cause you or your customers. Please feel free to contact me if you have any questions.

Thank you,

Pam Bauch

Product Specialist

1700 Finley Road  
Lombard, IL  
60148 USA

[cinch.com](http://cinch.com)