

Product Change Notification Form

Affected Part:	HMC660LC4B							
Description of Change: Discontinuation								
Product Change Category:								
Process	Form 🗌	Fit 🗌	Function	Reliability 🗌	Obsolete 🖂			
Reason for Change: End of product life (EOL) Impact to Customers: Hittite Microwave recommends replacing the HMC660LC4B with the HMC760LC4B. Although the recommended replacement does not provide the same fit, it does provide similar, to superior, function. Detailed information for this part can be found at www.hittite.com								
Means of Disting Changed Produ	• •	Part numbe	r					

Milestone Dates:

Qualification Samples Available	Qualification Data Available	Shipment of Changed Product	Last-Time Buy for Unchanged Product	Last-Time Delivery for Unchanged Product
6/22/2012	6/22/2012	6/22/2012	12/28/2012	6/28/2013

Hittite Microwave Corporation Contact: _

Please direct technical inquiries via email to <u>pcn@hittite.com</u>, <u>olav.lindquist@hittite.com</u> Please direct price, delivery, order status inquiries via email to <u>sales@hittite.com</u>

PCN120012.docx REV B ECN CP111529

