

To: Molex Sales Engineers, Customers and Authorized Molex Distributors

From: John Holba – Global Product Manager

Date: September 16, 2013

Subject: HD Mezz Product Change

As part of our continuous improvement activities, Molex is making a change to the guide pin to remove the swaging process and prevent potential metallic debris.


- Product Series Affected
- Details of Change
- Implementation dates

Product Series

Series	Description
45830	HD Mezz Plug
46743	HD Mezz Plug


Details of Change

- The change will have **no fit, form, or function** implications to the product.
- Product performance is consistent or better than the current product offering and no changes are required to the product specification.
- Part numbers will not be affected by this change.
- Guide pin retention will meet or exceed current levels.









Implementation Dates

• Integration of this change will begin as early as 10/31/2013.

If you have any questions or concerns, please feel free to contact me.

John Holba Global Product Manager 630-527-4838 John.Holba@molex.com