



Product Change Notification (PCN)

PCN Number	507099	Date Issued	May 30, 2019
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Reason for Short Notice	Force Majeure		
Assessment of Change	First article inspection		
Internal Molex Qualification Date	June 07, 2019		
Sample Availability Date (Changed Part)	June 07, 2019		
Planned Implementation Date	June 10, 2019		
Method of Identifying Change	Product made after planned implementation date can contain the change		

RELEASED

Before Change

previous



After Change

future



The position of the knurled part on the screw sleeve is in the direction of the cable outlet to the rear in order to achieve better handling during assembly. The knurled structure and length as well as the diameters remain the same.



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:507099**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN #	Molex Part #
507099	1300238029