

Product Obsolescence Notice

Dear customer,

Please be advised that the products listed in the table below are going obsolete and will not be remanufactured after the listed effective date. Future orders will be fulfilled until our inventory reaches zero parts on hand. We apologize for any inconvenience this may cause and we encourage you to contact Leader Tech with any questions or alternate material options.

Details of Obsolescence:

| | |
|--|--|
| Product Family | 1) Elastomers |
| P/N(s) Affected | 1) All Elastomer P/Ns using LTE-76 material |
| Product Description | 1) Conductive elastomer products (Leader Tech material LTE-76) (silicone material and silver filling). |
| Product Image | 1) N/A |
| Replacement(s) | 1) Leader Tech material code LTE-25, LTE-55 |
| Reason for Obsolescence | 1) Component costs outweighed sales benefits, low demand |
| Effective Date | 1) 11/2/2021 |
| Quantity on hand as of effective date | 1) 6.715 LBS |
| Additional Notes | 1) N/A |

Approvals:

| | | |
|-----------------------|-----------------------|------------|
| President | <i>Tracy R. Kuhns</i> | 11/04/2021 |
| VP Engineering | | |

If you have any questions regarding this notice, please feel free to contact us at 866-832-4364 or sales@leadertechinc.com.