

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M000994P

DATE: 21-May-2020

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommeded Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS1923-F5#W	DS1923-F5#	21-May-2021	21-May-2021	Part can no longer be manufactured
Discontinuance	MAX19526EXE+T	N/A	21-May-2020	21-May-2020	The part was not released
Discontinuance	MAX19528EXE+T	N/A	21-May-2020	21-May-2020	The part was not released
Discontinuance	MAX77962EWJ+	MAX77962EWJ06+	21-May-2020	21-May-2020	The part was not released
Discontinuance	MAX77962EWJ+T	MAX77962EWJ06+T	21-May-2020	21-May-2020	The part was not released