

## **Product Obsolescence Notification**

[10569577]

To: All active customers

From: Frederick Sia / fsia@molex.com / +65-6660-8571

cc:


Date October 25, 2012

**Product Family / Series:** VD / 78036, 78037, 78165, 78166, 78196, 78197

Part Numbers Affected: See below

**Product Description:** DLP Lamp Connector

**Product Image:** 







Replacements: No Replacement

Last Order Entry Date: April 1, 2013

Obsolescence Effective Date: April 25, 2013

For further information please contact your local sales representative.

## **PCN** Obsolesence special note:

If no last time buy orders are received by Molex within 180 days after issue date of the Obsolescence PCN, Molex reserves the right to terminate production at any time at it's own discretion. MOQ and lead time will be negotiated at time of order placement and will be dependent upon material availability. Molex will make all efforts to meet customer order requirements. Orders placed after Obsolescence Notification and subsequently cancelled will be subject to a cancellation charge.

Molex, Inc.

2222 Wellington Court Lisle, Il 60532

TEL: 630-969-4747 FAX: 630-

www.molex.com



## **Product Obsolescence Notification**

[10569577]

To: All active customers

From: Frederick Sia / fsia@molex.com / +65-6660-8571

cc:

Date October 25, 2012

Material Number	New XDChain
780361001	E2
780362001	E2
780362002	E2
780362003	E2
780362004	E2
780362005	E2
780362007	E2
780371001	E2
780372001	E2
780372002	E2
780372003	E2
780372004	E2
780372005	E2
780372007	E2
781651001	E2
781661001	E2
781961001	E2
781971001	E2

## Molex, Inc.

2222 Wellington Court Lisle, Il 60532

TEL: 630-969-4747 FAX: 630-