



Product Change Notification



Product Group: Vishay Dale/March 26, 2014/PCN-DI-194-2014 Rev 0

IHLW-4040CF-11 0.15uH data change

DESCRIPTION OF CHANGE: The data sheet is being changed to reflect the correct data. The electrical specifications of this part are changing to the tested values.

CLASSIFICATION OF CHANGE: Assembly Process/Structure

REASON FOR CHANGE: To correct error on the data sheet.

EXPECTED INFLUENCE ON QUALITY/RELIABILITY/PERFORMANCE: None.

PRODUCT CATEGORY: Inductors

PART NUMBERS/SERIES/FAMILIES AFFECTED: IHLW4040CFERR15M11

VISHAY BRAND(s): Vishay Dale

TIME SCHEDULE: Immediately

SAMPLE AVAILABILITY: Samples are available through normal sample process.

PRODUCT IDENTIFICATION: N/A

QUALIFICATION DATA: N/A

ISSUED BY: Doug Lillie, Product Marketing Manager

For further information, please contact your regional Vishay office.

CONTACT INFORMATION:

The Americas

Vishay Intertechnology, Inc
1505 East Highway 50
P. O. Box 180
Yankton, South Dakota 57078
Ph: 1 605-665-9301
Fax: 1 605-665-1627
doug.lillie@vishay.com

Europe

Vishay Electronic GmbH
Dr.-Felix-Zandman-Platz 1
95100 Selb
Germany
Ph: 49-9287-71-2282
Fax: 49-9287-71-2496
jens.walther@vishay.com

Asia

Vishay Asia Pte Ltd.
25 Tampines Street 92
Keppel Building #02-00
Singapore 528877
Ph: +65-788-6668
Fax: +65-788-3383
victor.goh@vishay.com