



Product Change Notification (PCN)

PCN Number	508585	Date Issued	March 26, 2020
Reason for Change	Change to Product		
Change Type Description	This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change may affect the fit, form, function or appearance of the parts, or it may result in a change to the specification. The pictures below show an example of the possible differences.		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports will be available after below listed date		
Internal Molex Qualification Date	March 13, 2020		
Sample Availability Date (Changed Part)	March 13, 2020		
Planned Implementation Date	September 26, 2020		
Method of Identifying Change	Date code		

RELEASED

Before Change

- 78727xxxx series product metal shell surface plating change from matt tin to nickel, the soldering tail plating still is matt tin, it's not effect to soldering. The surface status as below picture



1.27µmmin-2.54µm max. matte tin over 1.27µm min .nickel underplate over all



1.27µm min-2.54µm max. matte tin on solder tail over 1.27µm min. nickel underplate over all

After Change

Overview

- Due to internal quality improvement of the products for continuous quality enhancement activities, 78727xxxx series product metal shell surface plating change from matt tin to nickel.
- Product Impact**
It has no impact to fit, and function
- Part Number Impact**
787270001
787273001
787272001
- Qualification Reports and samples available upon request after the date shown above



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:508585**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN #	Molex Part #
508585	787270001