Amphenol Taiwan Corporation Product Change Notification

Part Numbers Concerned :	G40H3132211HRG40H2132211HRG40H3132211HR-CG40H2132211HRG40H3132211HR-DG40H2132211HR-IG40H3132211HR-FG40H2132211HR-IG40H3132212HRG40H2132212HRG40H3132212HR-BG40H2132212HRG40H3132212HR-CG40H2132212HR-IG40H3132212HR-FG40H2132212HR-IG40H3132212HR-FG40H2132212HR-IG40H3132212HR-FG40H2132212HR-IG40H3132212HR-FG40H2132213HRG40H3132221HR-CG40H2132213HRG40H3132221HRG40H2132222HFG40H3132212HR-KG40H2132222HF	F -L -C -W -C -D	Originator:	Walter Chien
Product	Mini SAS HD G40H2& G40H3 VT 1*1	Issue Date:		Oct. 26, 2020
Description:	Series		PCN NO:	P-20-001026
Distribution:	Change of Packaging to make it easier to unpack for customer			

Product Change Notice

Change of Packaging:

Remove the inner box to make it easier to unpack.

Before:







Background:

For the existing packing, the tape-reels are packed into the inner box before putting it into the outer carton, the customer need to open the inner packing to pick up the connectors, which is a waste of time, in order to make it easier to unpack for customer, Amphenol is intended to remove the inner box and put the tape-reels into the stronger outer carton directly, Secure all sides with cardboard, This change will not affect the function of the product.

Product Part Number Affected:

G40H3132211HR	G40H2132211HR	
G40H3132211HR-C	G40H2132211HR-C	
	• • • • • • • • • • • • • • • •	
G40H3132211HR-D	G40H2132211HR-F	
G40H3132211HR-F	G40H2132211HR-L	
G40H3132212HR	G40H2132212HR	
G40H3132212HR-B	G40H2132212HR-C	
G40H3132212HR-C	G40H2132212HR-W	
G40H3132212HR-F	G40H2132213HR-C	
G40H3132221HR-C	G40H2132213HR-D	
G40H3132221HR	G40H2132222HR	
G40H3132212HR-K		
The second secon		

Implementation date:

Use products with new packaging by running change from 2020/12/1

Recommended Action:

• Sales inform customers of this packaging change notification.