



## Product Discontinuance Notice - PDN 12\_0132 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

### PDN Title:

Obsolescence of Selected TMP05 and TMP06 parts

**Publication Date:** 07-Sep-2012

**Last Time Buy Date:** 28-Feb-2013

**Last Time Ship Date:** 28-Aug-2013

### Reason For Discontinuance

We have reviewed our portfolio of products based on run rate and availability of alternative parts. This review has resulted in the discontinuance of these models.

### Comments

All recommended replacements are the lead free equivalent of the above parts.

**Supporting Documents** None

**For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative**

**Americas:** PDN\_Americas@analog.com

**Europe:** PDN\_Europe@analog.com

**Japan:** PDN\_Japan@analog.com

**Rest of Asia:** PDN\_ROA@analog.com

### PDN 12\_0132 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
TMP05ART-500RL7	TMP05	TMP05ARTZ-500RL7	Yes	
TMP05ART-REEL	TMP05	TMP05ARTZ-REEL7	Yes	
TMP05BRT-500RL7	TMP05	TMP05BRTZ-500RL7	Yes	
TMP05BRT-REEL	TMP05	TMP05BRTZ-REEL	Yes	
TMP06ART-500RL7	TMP06	TMP06ARTZ-500RL7	Yes	
TMP06ART-REEL7	TMP06	TMP06ARTZ-500RL7	Yes	
TMP06BRT-500RL7	TMP06	TMP06BRTZ-500RL7	Yes	
TMP06BRT-REEL	TMP06	TMP06BRTZ-500RL7	Yes	

Appendix A - PDN 12\_0132 Revision History

Rev	Publish Date	Rev Description
Rev. -	07-Sep-2012	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:567 Layout Rev:2 Parent DocId:None