

PRODUCT CHANGE NOTIFICATION

PCN#: CABLE COPPER, FIBER CABLE AND CONNECTORS **20190220-004**

ISSUE DATE: 19-Feb-19

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Not Required for discontinuation)

Sales have declined. Please change to "Use up/OBS" and replace with "where applicable" Composite Ferrule OptiCam connectors will be discontinued in favor of more commonly used connectors such as OptiCam and Fusion Splice connectors.
 ability of more applicable products has necessitated this discontinuation."

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2018	2	18
Old product discontinuation date*	2019	2	18

***Important:** After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product continuation date.

IMPACTED PART NUMBER(s)	REPLACEMENT PART NUMBER(s)
FSCMPC6BL	FSC2MC6EI
FSCMPC6BL-C	FSC2MC6EI-C
FSCMPC6BLG	None
FSCMPC5BL	FSC2MC5BL
FSCMPC5BL-C	FSC2MC5BL-C
FSCMPC5BLG	None