

Global Change Notification (GCN)

Product Family	HDM BP	10656140
		GCN Number
Series	Various	September 23, 2014
		Date Issued
Reason For Change	Obsolescence	
Change Description	This letter is to inform you that due to low volume Molex will be discontinuing several HDM BP Part numbers without replacement. This change will affect the following series: 73650, 73769, 73770, 73771, 73781, 73782, 73783, 74428, and 74993.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception		
Assessment Of Change (How Product Will Be Qualified & Validated)	No replacement parts will be available.	
Internal Molex Qualification Date (Planned Date Information Available)		
Sample Availability Date (Changed Part)		
Date of Implementation	September 30, 2015	
Method of Identifying Change	N/A	
Recommended Replacement Parts		
Last Time Buy Date for Obsolete Parts	December 31, 2014	
Last Time Ship Date for Obsolete Parts	June 30, 2015	

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com