



Date: 03.12.2021

URGENT NOTIFICATION – Recall of Part Number ABM8AIG-12.000MHZ-12-2Z-T3 Lot Code 135882

Dear Valued Customer,

Abracon regrets to inform you that we are invoking an official recall for order 3138267 containing four reels of ABM8AIG-12.000MHZ-12-2Z-, Lot Code 135882 that were sold to Digi-Key. The parts are highly suspect of having a different ppm tolerance. Even though all the parts will measure the correct frequency, there is a possibility the some of the pieces have slightly different \pm ppm frequency tolerance than others. Therefore, not being true to the part specification.

Please work with the end customer to appropriately quarantine any unused parts. Abracon is requesting if you could please submit an RMA request attached to this email for the available inventory to provide you with credit. Your Abracon Customer Service Representative can help to place any replacement orders. We apologize for this inconvenience and trouble.

Respectfully,



Francisca Robbe *Quality Engineer*
Office: 512.317.6159 x 1476
Address: 5101 Hidden Creek Ln, Spicewood, TX 78669



Form 8026 - Rev C - Effective Date: 11/19/2020

