

# Dear Valued Lantronix Customer,

The purpose of this communication is to inform you of an upcoming change to the following product. This change is part of our effort and commitment to continuous improvement of our products and processes.

### Change Type

Software

# Product Affected

Part Number	Description	Old Revision	New Revision
PXC2102H2-01	PREMIERWAVE XC HSPA+ APPLICATION/DEVICE SERVER, MODEL LEVEL	D13	E13
PXC2102H2-01-B	PremierWave XC HSPA+ Intelligent Gateway, 64MB Flash, DC Power Cable, RoHS, 20-pc Bulk	B13	C13
PXC2102H2-01-S	PREMIERWAVE XC HSPA+ APPLICATION/DEVICE SERVER	D13	E13

### **Description and Extent of Change**

Lantronix is pleased to announce the release of Application Firmware version 8.2.0.0R2. This new firmware offers several new features and improvements including:

• SB-327 Compliance

Refer to the release notes for a complete list of additional features.

For customers that would like to take advantage of the new capabilities immediately, the new firmware, associated release notes and upgrade instructions is available for download from our website, <u>http://www.lantronix.com/support/downloads</u>.

### Effect of Change on Fit, Form, or Function

Functional changes as noted above.

# Effective Date of Change

The affected products with the above changes will begin shipping from the factory by Jan 1 2020.

If you have any questions, please contact your sales representative or Lantronix Technical Support at (800) 422-7044 or (949) 453-7198.

7535 Irvine Center Drive | Suite 100 Irvine, CA 92618 USA

800.526.8766