



PRODUCT DISCONTINUATION

PD-IFC-LXJ0-15

Business Unit	Product Line Code	Type of Change	Action	Date of issue
IFC	BF7	Discontinuation	Notify	5/6/2015
			Distributors and	
			Field	

Phoenix Contact's factory has announced the following product(s) is going to be discontinued. Existing specifications will be met or exceeded. Technical support of the discontinued product will continue, as required. Please review and acknowledge this document and take the appropriate action with respect to your existing inventory and ordering replacement parts.

Reason for Discontinuation:

Phoenix Contact is committed to proving our customers the best-in-class products and services. We strive to provide accurate product information and announce any product changes in a timely manner. For this reason we are contacting you regarding a necessary product obsolescence. We have implemented improvements to our manufacturing process and will be replacing the following Heavycon inserts with the attached direct equivalents.

Warranty Information:

N/A

Stock Status

Can existing stock still be used? Y

Is mixture of stock acceptable? Y

Transaction Dates:


Last Buy from Phoenix Contact: 9/30/2015

Last Scheduled Ship from Phoenix Contact: 10/30/2015



INSPIRING INNOVATIONS Phoenix Contact Inc. P.O. BOX 4100 Harrisburg, PA 17111-0100 Phone: 717-944-1300 Fax: 717-944-1625

PRODUCT DISCONTINUATION



Should you have any issues with the timeline or content of this discontinuation, please contact Phoenix Contact using the contact information below. Customers should acknowledge receipt of the PD within 30 days of delivery of the PD; provided, however that the failure to acknowledge receipt does not affect the product discontinuation or the effective date thereof.

Contact Info:

STEVEN OBERT IFC Marketing Lead Specialist (717)944-1300x3250 sobert@phoenixcon.com

Thank you,

Kneen Ed

Loreen E. Katz, Product Marketing Manager





Phoenix Contact Inc. P.O. BOX 4100 Harrisburg, PA 17111-0100 Phone: 717-944-1300 Fax: 717-944-1625

PRODUCT DISCONTINUATION

Discontinued Part#	Type Description	Replacement Part#	Type Description
1687435	HC-BB 10-EBUC	1584703	HC-BB10-I-CT-F
1687448	HC-BB 10-ESTC	1584774	HC-BB10-I-CT-M
1687451	HC-BB 18-EBUC	1584729	HC-BB18-I-CT-F
1687477	HC-BB 32-EBUC	1584745	HC-BB32-I-CT-F
1687480	HC-BB 32-ESTC	1584732	HC-BB32-I-CT-M
1687493	HC-BB 46-EBUC	1584758	HC-BB46-I-CT-F
1687503	HC-BB 46-ESTC	1584761	HC-BB46-I-CT-M
1687820	HC-B 5-EBUC	1406537	HC-Q05-I-CT-F
1687817	HC-B 5-ESTC	1406538	HC-Q05-I-CT-M