

## PRODUCT CHANGE NOTIFICATION


Date: May 3, 2021  
PCN: PCN LEDIL 171

Subject: PCN 171 - Correction of product mechanical drawing

Description: As part of our continuous improvement process regarding the quality of our products, LEDiL has corrected incorrect information on the mechanical drawing of CP17590\_LEILA-SC-O-90. Light distribution orientation indicator mark has now been updated in the right direction.

Timeline: This change is valid immediately.

Changes: CP17590\_LEILA-SC-O-90 mechanical drawing update.  
Updated light distribution direction mark orientation.



### Contact information:

Kalle Hannila  
Product Manager  
Joensuunkatu 13  
24100 SALO, FINLAND  
[kalle.hannila@ledil.com](mailto:kalle.hannila@ledil.com)

Veijo Isojunno  
Product Manager  
Joensuunkatu 13  
24100 SALO, FINLAND  
[veijo.isojunno@ledil.com](mailto:veijo.isojunno@ledil.com)

Kirsikka Dräger  
Marketing Manager  
Joensuunkatu 13  
24100 SALO, FINLAND  
[kirsikka.drager@ledil.com](mailto:kirsikka.drager@ledil.com)

Samuli Saransalmi  
Marketing Manager  
Joensuunkatu 13  
24100 SALO, FINLAND  
[samuli.saransalmi@ledil.com](mailto:samuli.saransalmi@ledil.com)