



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000778

DATE: 23-May-14

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Discontinuance	DS21458DK	DS26518DK	23-May-2014	22-May-2016	The eval kit is no longer supported
Discontinuance	DS2151QB+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2151QBX2	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2152L+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2152LN+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2153Q-A7+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2153Q-A7+T&R	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2153QN-A7+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2164Q+T&R	N/A	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	DS2175S+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2180AQ+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2180AQ+T&R	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2180AQN+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2180AQN+T&R	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2188+	N/A	24-Nov-2014	23-Nov-2016	Part is leaded, and a lead-free replacement exists
Discontinuance	DS2188S+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS2188SN+T&R	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS21FF44N	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS21FT42N	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS21FT44N+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	DS33X162DK	N/A	23-May-2014	22-May-2016	The part was not released
Discontinuance	DS33X42DK	N/A	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	DS33Z11DK	N/A	23-May-2014	22-May-2016	The part was not released
Discontinuance	DS4077L-0CN	N/A	23-May-2014	22-May-2016	The part was not released
Discontinuance	DS4077L-BDN	N/A	23-May-2014	22-May-2016	The part was not released
Discontinuance	DS4077L-DCN	N/A	23-May-2014	22-May-2016	The part was not released
Discontinuance	DS4077L-FCN	N/A	23-May-2014	22-May-2016	The part was not released
Discontinuance	MAX1471ATJ	MAX1471ATJ+T	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX1471ATJ-C3N	MAX1471ATJ+C3N	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured

Discontinuance	MAX1471ATJ-T	MAX1471ATJ+T	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX14972CTG+	N/A	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX14972CTG+T	N/A	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX14975ETG+	MAX14966EWT+	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX14975EVKIT#	MAX14966EVKIT#	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX15068EVKIT+	N/A	23-May-2014	22-May-2016	The eval kit is no longer supported
Discontinuance	MAX15109EVKIT#	MAX15108AEVKIT#	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX15109EWP+	MAX15108AEWP+	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX15301EVKIT#	MAX15301EVKITHP#	23-May-2014	22-May-2016	The eval kit is no longer supported
Discontinuance	MAX16914AUB/V+	N/A	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX16914AUB/V+T	N/A	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX16963RATEA+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX1724EVKIT	MAX1724EVKIT+	23-May-2014	22-May-2016	The eval kit is no longer supported
Discontinuance	MAX17802EWG+T	N/A	23-May-2014	22-May-2016	The part was not released
Discontinuance	MAX1984ETP+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX1985ETP+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX1986ETE+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX20080ATM/V+	MAX20080ATM/V+CFT	24-Nov-2014	23-Nov-2016	The part was not released
Discontinuance	MAX20080ATM+TG2Z	MAX20080ATM/V+TCFT	24-Nov-2014	23-Nov-2016	The part was not released
Discontinuance	MAX20091ATM/V+G2Z	MAX20091ATM/V+	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX2550ETN+TW	MAX2550ETN+T	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX2550ETN+W	MAX2550ETN+	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX2552ETN+TW	MAX2552ETN+T	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX2552ETN+W	MAX2552ETN+	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX4027ESD	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX4027EUD+T	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX5051AUI+	MAX5051AAUI+	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX5051AUI+T	MAX5051AAUI+T	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	MAX7449EUD+	N/A	24-Nov-2014	23-Nov-2016	Part can no longer be manufactured
Discontinuance	MAX846EVKIT	MAX846EVKIT+	23-May-2014	22-May-2016	The eval kit is no longer supported
Discontinuance	MAX9713EVKIT+	MAX9713EVKIT	23-May-2014	22-May-2016	The part was not released
Discontinuance	MAX98357EVKIT#WLP	MAX98357DEV#WLP	23-May-2014	22-May-2016	The part was not released
Discontinuance	MX536AJH+	N/A	23-May-2014	22-May-2016	Part can no longer be manufactured
Discontinuance	SD220+122T	SD220+123T	23-May-2014	22-May-2016	Part can no longer be manufactured