

To all concerned customers

Bosch Sensortec GmbH
 Visitor:
 Gerhard-Kindler-Straße 9
 72770 Reutlingen
 Tel 07121 3535-900
 www.bosch-sensortec.com

Bosch Sensortec GmbH
 Product Management

14 June 2021

Discontinuance Notification

Application boards with and without bluetooth and respective shuttle boards, sales part numbers see table below

Ladies and Gentlemen,

We would like to inform you that we are discontinuing our current application boards with and without bluetooth and the respective shuttle boards effective immediately. The current evaluation tools are going to be replaced by a new application/shuttle board version.

Discontinued		Replacement	
Sales Part Number	Board	new Sales Part Number	Board
0330.SB6.310	Shuttle Board BHA250B	no replacement, BHA250B discontinued	
0330.SBL.392	Shuttle Board Set BHA260AB	0440.SB6.392	BHA260AB Shuttle Board 3.0
0330.SB6.309	Shuttle Board BHI160B	0440.SB6.309	BHI160B Shuttle Board 3.0
0330.SBL.367	Shuttle Board Set BHI260AB	0440.SB6.367	BHI260AB Shuttle Board 3.0
0330.SB0.001	Shuttle board BMA253	no replacement, BMA253 not for new designs	
0330.SB0.148	Shuttle Board BMA280	no replacement, BMA280 not for new designs	
0330.SB0.275	Shuttle Board BMA400	0440.SB0.275	BMA400 Shuttle Board 3.0
0330.SB0.292, 0330.SB0.016	Shuttle Board BMA423	no replacement, BMA423 discontinued	
0330.SB0.282	Shuttle Board BMA456	0440.SB0.282	BMA456 Shuttle Board 3.0
0330.SB0.021	Shuttle Board BMA490L	0440.SB0.021	BMA490L Shuttle Board 3.0
0330.SB4.185	Shuttle Board BME280	0440.SB4.185	BME280 Shuttle Board 3.0
0330.SB4.312	Shuttle Board BME680	0440.SB4.312	BME680 Shuttle Board 3.0
0330.SB4.016	Shuttle Board BME688	on request, dedicated evaluation kit available	

Discontinued		Replacement	
Sales Part Number	Board	new Sales Part Number	Board
0330.SB5.235	Shuttle Board BMF055	no replacement, BMF055 not for new designs	
0330.SB3.064	Shuttle Board BMG250	no replacement, BMG250 not for new designs	
0330.SB2.134	Shuttle Board BMI055	no replacement, BMI055 not for new designs	
0330.SB2.366	Shuttle Board BMI085	0440.SB2.366	BMI085 Shuttle Board 3.0
0330.SB2.365	Shuttle Board BMI088	0440.SB2.365	BMI088 Shuttle Board 3.0
0330.SB2.020	Shuttle Board BMI090L	0440.SB2.020	BMI090L Shuttle Board 3.0
0330.SB2.187	Shuttle Board BMI160	no replacement, BMI160 not for new designs	
0330.SB2.008	Shuttle Board BMI270	0440.SB2.008	BMI270 Shuttle Board 3.0
0330.SB0.157	Shuttle Board BMM150	0440.SB0.157	BMM150 Shuttle Board 3.0
0330.SB1.436	Shuttle Board BMP280	no replacement, BMP280 not for new designs	
0330.SB1.015	Shuttle Board BMP384	0440.SB1.015	BMP384 Shuttle Board 3.0
0330.SB1.511	Shuttle Board BMP388	no replacement, BMP388 not for new designs	
0330.SB0.179	Shuttle Board BMX055	no replacement, BMX055 not for new designs	
0330.SB0.190	Shuttle Board BMX160	0440.SB0.190	BMX160 Shuttle Board 3.0
0330.SB5.209	Shuttle Board BNO055	0440.SB5.209	BNO055 Shuttle Board 3.0
0330.SBx.xxx	all other old generation Shuttle Boards	tbd	
0330.AB0.111	Application Boards with BT	0440.AB0.111	Application Board 3.0
0330.AB0.011	Application Boards without BT	no replacement	

Please note that the lead-time for the different shuttle boards varies.

Yours sincerely

Bosch Sensortec GmbH

i.V. _____
 Ralf Schellin
 Head of Product Area MEMS

ppa. _____
 Mark James Johnson
 Vice President Sales