Sensing and Control



Notification of Obsolescence

Notification Date: June 23, 2014

Obsolescence Notification Number: EOL1005

Affected Part Numbers: OP641SL, OP642SL

Effective Date of Obsolescence: Immediately

Last Time Buy Last time buy will be limited to inventory on hand and distributor

returns.

Recommended Replacement(s): No recommended replacement for OP641SL or OP642SL

currently exists.

Factory Backlog: Factory Backlog may be affected. Contact your Customer Service

Representative for details.

Distributor Inventory: Under the terms of our distributor agreement, existing inventory

may be returned for credit. RMA's may be requested from your Optek Customer Service Representative. Return requests must include quantity, part number, acquisition cost, purchase order number and date received. Requests for return must be

received within thirty (30) days of this notification. Requests for return received beyond thirty (30) days will not be considered.

Obsolescence Authorization:

Jeff Beatty

Product Marketing Specialist Optoelectronics Business Unit