



Product Change Notification

TE Connectivity

Product Change Notification: P-20-018820

PCN Date: 23-MAR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

AMP MCP 2 8

Description of Changes

Standardization of the silver material for the AMP MCP 2.8. The Plating has changed in the connection area from Ag to Sn (state of the art for connection areas). The base material and the plating in the contact area remain the same. AMP MCP 2.8 Revision E revised to Rev F for all silver variants, except PN 1-2141857-3, PN 1-2141858-3, PN 1-2141859-3, PN 1-2141860-3, PN 1-1719506-3, PN 1-2282364-3, PN 1-2236751-3 and PN 1-2236752-3 revised from Rev A to Rev B.

Reason for Changes:

Part status change. The new silver-plating material for the AMP MCP 2.8 is already used for the 2 8mm SFC. This increases the delivery reliability of the silver material.

Estimated Dates:

Last Order Date (Obsolete Parts Only): **First Date To Ship** (Changed Parts Only):

01-SEP-2020

Last Ship Date (Obsolete Parts Only): **Last Date for Mixed Shipments:** (Changed Parts Only):

01-DEC-2020

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1719506-3	NO						
1-2282364-3	NO						
1-968849-3	NO						
1-968851-3	NO						
1-968853-3	NO						
1-968855-3	NO						
1-968857-3	NO						
1-968859-3	NO						
1-968880-3	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968849-3	NO						
1-968851-3	NO						
1-968853-3	NO						
1-968855-3	NO						
1-968857-3	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968849-3	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-968853-3	NO						
1-968855-3	NO						
1-968857-3	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1719506-3	NO						
1-2282364-3	NO						
1-968851-3	NO						
1-968853-3	NO						
1-968857-3	NO						
1-968859-3	NO						
1-968880-3	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1719506-3	NO						
1-2282364-3	NO						
1-968851-3	NO						
1-968853-3	NO						
1-968857-3	NO						
1-968859-3	NO						
1-968880-3	NO						