

TE Connectivity

Product Change Notification: P-19-017554 PCN Date: 26-JUN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
MINI MLC CAP HSG ASSY 7P

Description of Changes
Supplier change of component "Seal Rubber" from Japanese to Korean supplier. Other manufacturing site and process are not changed.

Reason for Changes:

Product improvement.Multi sourcing including risk management, If you have any questions, please contact Kotake, Kenji <kkotake@te.com>.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

01-OCT-2019

Last Ship Date (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2822344-1	NO						
2822344-4	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2822344-1	NO						
2822344-4	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2822344-1	NO						
<u> 2822344-4</u>	NO						