

# Product/Process Change Notification PCN07117

Product:	Micropax Connectors	Part Numbers Concerned:	See list attached
Product Manager:	David Hansen	Issue Date:	11 July 2007
		Page(s):	1/1
Distribution:	GLOBAL		

### Subject:

Micropax Connectors; Resin Change on Pickup Caps

# Nature of Change:

FCI is upgrading the plastic used on pickup caps for some Micropax part numbers. This upgrade increases the product's heat tolerance during IR-reflow assembly processing.

## Old resin used for pickup cap:

PPS 40% glass-filled; UL Rated 94V-0; Color: Black

## New resin used for pickup cap:

LCP 30% glass-filled; UL Rated 94V-0; Color: Vanilla

### Impact of change:

None. All Micropax connectors will continue to meet or exceed current performance specifications.

# **Implementation Date:**

Immediate to accelerate product upgrade and increase customer satisfaction.

### **Affected Part Numbers:**

See attached list

# For questions regarding this PCN contact:

David Hansen Product Manager

Phone (Mexico): (011) 52 656 692 5812 E-Mail: <a href="mailto:david.hansen@fciconnect.com">david.hansen@fciconnect.com</a> Or contact your nearest FCI representative