



Product Change Notification (PCN)

PCN Number	507598	Date Issued	October 16, 2019
Reason for Change	Manufacturing Process Change (Molex)		
Change Type Description	This letter is to inform you that the manufacturing process for the part(s) identified in this notice is changing. No changes will be made to the product as a result of this process change.		
Reason for Short Notice	New Capacity		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports will be available after below listed date		
Internal Molex Qualification Date	December 20, 2019		
Sample Availability Date (Changed Part)	December 20, 2019		
Planned Implementation Date	December 20, 2019		
Method of Identifying Change	Date code		

RELEASED

Before Change

After Change

Before	After
manual production line	automated production line

Overview

- Nano-Fit Series 105314 will be increasing capacity by moving to automated assembly
- Product/Process Impact
 - No impact to fit, form or function
- Part Number Impact
 - See attached impacted parts list
- Qualification Reports and samples available upon request after the date shown above



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:507598**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN #	Molex Part #
507598	1053141104
507598	1053141106
507598	1053141108
507598	1053141110
507598	1053141112
507598	1053141114
507598	1053141116
507598	1053141204
507598	1053141206
507598	1053141208
507598	1053141210
507598	1053141212
507598	1053141214
507598	1053141216
507598	1053141304
507598	1053141306
507598	1053141308
507598	1053141310
507598	1053141312
507598	1053141314
507598	1053141316
507598	1053142104
507598	1053142106
507598	1053142108
507598	1053142110
507598	1053142112
507598	1053142114
507598	1053142116
507598	1053142204
507598	1053142206
507598	1053142208
507598	1053142304
507598	1053142306
507598	1053142312
507598	1053142316

Part numbers affected:

105314-1104
105314-1106
105314-1108
105314-1306
105314-2308