

Date: 07.03.2019

EOL Ref No: 0002

Subject: LC200-UMTS(EU)

Details of replacement parts, where available, are specified below. The change method details where small volume stocks of discontinued parts remain in stock. Orders for discontinued parts will be switched to replacement parts and notified at time of order.

Product Affected:

Part Number: 60272	Replacement: 60270	Change Method
LC200-UMTS(EU)	LC300-UMTS	
Reason for change:	Manufacturing change	
LC300 modem provides additional functionality		N/A
Availability Date	Last Shipment Date	
Not Applicable	While stocks last	
See reference documentation below for additional notes and guidance		
File Name:LC300 Series HW Manual	Description: HW Manual	
File Name:LC300-UMTS Datasheet	Description: Datasheet	