

	CORPORATION			100200				
	CUSTOMER	CUSTOMER DRAWIN	USTOMER DRAWING OR PART NUMBER		REV. NO.	TODAYS DATE		
						2/1/2019		
	JKL PART NUMBER(s)	PART DESCRIPTION	ART DESCRIPTION		Part Family			
	7945	T-1 3/4 Bi Pin Lamp, 6V			T-1 3/4 Bi Pin			
		' '		I				
	JKL CONTACT NAME	PHONE		EMAIL:				
	REASON FOR NOTICE:							
	This lamp is no longer being produced.							
1								
Obsolete Item:			Suggested Replacement Item:					
	7945		7380					

Obsolete Item:	Suggested Replacement Item:			
7945	7380			
This lamp is rated at:	The suggested replacement lamp is rated at:			
6.0V .040A .030 MSCP	6.3V .040A .030 MSCP			
	This lamp can be run at 6.0V and is equivalent.			
	Mechanically it is the same.			
	No notable differences.			