

PRODUCT CHANGE NOTIFICATION

Product Category COMPUTER PRINTABLES 20221102-1

Product Group ID AND SAFETY

ISSUE DATE: 2-Nov-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

The old TDP43HE and TDP46HE model printers will be discontinued and replaced by the new TDP43HET and TDP46HET model printers. The old TDP43HE and TDP46HE printers will be available only while supplies last.

The old TDP43HE and TDP46HE printers will continue to be supported with Technical and Repair Assistance through the Panduit Identification Products Technical Support Team.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2022	10	31
Old product discontinuation date*	2022	11	4

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Discontinuation Date
TDP43HE	Compatible	TDP43HET	4-Nov-22
TDP43HE/E	Compatible	TDP43HET/E	4-Nov-22
TDP46HE	Compatible	TDP46HET	4-Nov-22