

Product Change Notification (PCN)

506756 Date Issued June 13, 2019 **PCN Number**

Reason for Change Packaging Method/Quantity Changing

Change Type Description This letter is to inform you that the part(s) referenced in this notice will undergo packaging specification changes that may include new container sizes, quantities or changes to the label.

No changes will be made to the product as a result of this change.

Assessment of Change No change to parts/components FFF

Internal Molex Qualification Date December 10, 2019


> Sample Availability Date December 10, 2019 (Changed Part)

Planned Implementation Date December 10, 2019

Before Change

After Change

MX150 Terminals DU Change



Overview

- MLQ/DU increasing for MX150 Terminals
 - Standardizing MLQ and DU values to align with packaging standard and ensure product quality. Support of the environment by reducing significant amount of packaging waste customers may face. Improve customer service by reducing errors in ordering/delivery
 - Help reduce lead-time

 - MLQ/DU changes
- Product Impact
- Assembly Part Number Impact

 No change to part numbers

 Part numbers impacted: See list

molex



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:506756" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

PCN #	Molex Part #
506756	330000002
506756	330000004
506756	330112002
506756	330113002
506756	330122001
506756	330122003
506756	330122021
506756	330122022
506756	330123022
506756	330123023
506756	340801003
506756	340832001
506756	347811004