

Product Change Notice

| | |
|-------------------------|---|
| Date: | November 30, 2022 |
| Overview: | Select models are being discontinued due to low global demand and ongoing optimization of our product portfolio |
| Reason for Change: | Low global demand and ongoing optimization of our product portfolio |
| Affected Part No(s): | Please see part number listing on Page 2 of this PCN |
| Design Change Detail: | N/A |
| Effective Date: | Immediately |
| Last Time Buy Deadline: | N/A |
| Pricing: | N/A |
| ebm-papst employee: | Jeannine Zenobi |
| Attachments: | Part number listing |
| Comments: | There are no direct replacements available; please contact us for an alternate recommendation based on your application |

| | | |
|--------------------------------|---------------------------|-------------------------------|
| Form No: 1274 | Quality Record - No | Page 1 of 1 |
| Rev. – Orig, Released 08/28/14 | Retention Period – 1 year | Dept. Owner – Sales/Marketing |

Affected Part Numbers

| | | | |
|--------------------|------------------|-------------------|--------------------------|
| 2214F/2TDHOU-754 | 4312N/2H3PU-755 | 6314/2TDHP-298 | QG030-353/14-024 |
| 2218F/19TDH4OR-235 | 4312N/2M-030 | 6318/19HPU-229 | QG030-353/14-040 |
| 2218F/2TDH4O-236 | 4314 HR-585 | 6318/2HA-219 | REF100-11/14/2PR-223 |
| 2218F/2TDH4OR-225 | 4314NHU-759 | 6318/2TDH4P-028 | REF100-11/14/2R-017 |
| 2218F/2TDH4OU-224 | 4314NNU-752 | 6318/2TDH4P-041 | REF100-11/14/39U-009 |
| 2218F/2TDH4PR-220 | 4412F/2G-527 | 6318/2TDH4P-053 | REF100-11/18HTU-194 |
| 2218F/2TDH4PU-232 | 4412F/2GMLPR-581 | 6318/2TDHHP-032 | RER101-36/12N/12HHA-182 |
| 2218F/2TDHHP-204 | 4412F/2GPR-209 | 6318N/2TDH3P-306 | RER101-36/12N/12HHA-197 |
| 255N-234 | 4412F/2GMLPR-581 | 6318TDHHP-056 | RER101-36/12N/12HHP-200 |
| 3212J/2H4P-218 | 4412F/2GPR-209 | 634/39HHU-191 | RER101-36/18N/2HHP-187 |
| 3212J/2HHP-001 | 4412FGLLA-193 | 638/2HHP-184 | RER125-19/12N/2TDPR-305 |
| 3214J/39H4-210 | 4412FGML | 638/2HHP-185 | RER125-19/12NG-156 |
| 3214JNPR-187 | 4412FM-502 | 6424/2HPR-235 | RER125-19/14N/2HU-179 |
| 3218J/2H4AR-00001 | 4412FML-465 | 6424HU-452 | RER160-28/14N/2AR-209 |
| 3218J/39H3P-199 | 4412ML-583 | 6448/2TDP-378 | RER175-39/18/2TDOR-00085 |
| 3218JH3-194 | 4414/2HHA-227 | 6448-384 | RER175-42/14/2TDMLP-621 |
| 3254J/2H3PU-025 | 4414/2HHP-202 | 6454/2TDHPU-309 | RER175-42/18/2TDMOR-105 |
| 3254JHU-028 | 4414F/2L-575 | 7114N-153 | RER175-42/18/2TDP-110 |
| 3312/37-497 | 4414FD-511 | 712F-011 | RER190-39/18/19TDMP-213 |
| 3412N/2HH-490 | 4414FL-569 | 7212N-459 | RER190-39/18/2TDOR-233 |
| 3412N/2HU-529 | 4414FN/2N-007 | 8212J/37NPR-184 | RER190-39/18/2TDP-231 |
| 3412NGHH-472 | 4414N-615 | 8312/2HPU-589 | RER190-39/18/2TDPR-224 |
| 3412NLR-469 | 4414N-629 | 8312/2L-155 | RER190-45/18/2TDAR-212 |
| 3412NM-396 | 4418/2M-547 | 8412 NGMLE-611 | RET90-18/14N-452 |
| 3414N/2HH-640 | 4418/2MPR-199 | 8412N/2G-280 | RET97-25/14/2TDMLOR-057 |
| 3414NGHH-625 | 4418HHI-231 | 8412N/2G-626 | RET97-25/18/2TDMPU-051 |
| 3414NH-616 | 4606ZWU-845 | 8412N/2G-648 | RG160-28/12/2NP-214 |
| 3414NLR-499 | 4850 Z-971 | 8412N/2H-581 | RG160-28/18NTDTU-352 |
| 3956 LWR-125 | 5114N/SU-057 | 8412N/37NI | RG220-43/14/2TDMO-307 |
| 4112N/12GL-175 | 514F/2-535 | 8412N-572 | RG90-18/14NG-233 |
| 4114N/2H7P-020 | 5212N/2TDHP-604 | 8412N-572 | RL48-19/14/2P-182 |
| 4114N/2H7P-029 | 5212N/2TDHPR-601 | 8414N/2-497 | RL65-21/14/37HP-181 |
| 4114N/2H8P-027 | 5214NHIR-194 | 8414N/2GL-00044 | RL65-21/18/2HPR-180 |
| 4114N/2HHP-358 | 5218N/2HPU-208 | 8414N-193 | RLF100-11/12-067 |
| 4114N/2XH4U-366 | 5318/2TDH4P-508 | 8414NGML-590 | RLF100-11/14/2P-216 |
| 4114NH6U-336 | 5656S-012 | 8414NM - 547 | RLF100-11/14/2PR-222 |
| 4114NHU-282 | 6078 ES-000 | 8418N/2HP-184 | RLF100-11/14/37PR-214 |
| 4118N/19HTU-355 | 612F-686 | 8452/2H4P-185 | RLF35-8/12/2HP-113 |
| 4118N/2H3AR-281 | 612FL-647 | 8454/19H4-187 | RLF35-8/12N/2-124 |
| 4118N/2H5PR-361 | 612FL-648 | 9956-011 | RLF35-8/12N/2P-129 |
| 4118N/37H6TR-346 | 612FLR-702 | ACi 4400 HHR-508 | RLF35-8/14N/2P-125 |
| 412/2HP-128 | 612FLR-704 | ACi 4400 HHU-503 | |
| 412F/2M-168 | 612N/2GL-090 | ACi 4420 LU-016 | |
| 412F-164 | 612NME-209 | ACi4400HH-00103 | |
| 412FM-152 | 614N/2GH-255 | DV4112/2NP-201 | |
| 412J/2-043 | 614NM | DV4114NPU-220 | |
| 414 F-112 | 6224NR-184 | DV5214/2NA-229 | |
| 414 FH-099 | 624 HHPR-195 | DV6318/2TDH4P-101 | |
| 414JH-047 | 624/2H3P-208 | DV6448/2A-209 | |
| 424J/2HP-017 | 624/2N-102 | QG030-148/14-016 | |
| | 6248NMR-242 | QG030-303/14-041 | |