

## INSPECTION LIST

- Verify that wire cut length is 12" ± .25".
- Verify that cable is labeled VL-CBL-5008.
- Verify that there are center polarization tabs.
- Verify that IDC connectors are properly crimped.
- Verify that mounting rings are with clips (one pair).
- Verify COM ports, mouse and keyboard labels.
- Verify that reset switch has white stem.

## NOTES

HP-T1M



## ASSEMBLY

