

General Product Description:

TE Connectivity

Product Change Notification: P-18-016659 PCN Date: 29-NOV-18

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

MCP-E REC

Description of Changes

Slot holes add to improve camber/twist of carrier

Other attachments:

MCP-E REC

Reason for Changes:					
Product improvement.There are no changes to the product.					
Estimated Dates:					
Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):				
	03-DEC-2018				
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):				
	30-SEP-2019				

Part Number(s) being Modified:

Part Number	Part Discontinued per	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias Part	Description Of
Part Number	PCN	Drawing	Number	Number(s)	Number	Number(s)	Difference
<u>1743163-1</u>	NO						
<u>1743465-1</u>	NO						
936606-1	NO						
936607-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1743163-1	NO						
1743465-1	NO						
936606-1	NO						
936607-1	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1743163-1	NO						
<u>1743465-1</u>	NO						
936606-1	NO						
936607-1	NO						