Product Discontinuance Notice - PDN 18_0011 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Add additional obsolete FG part numbers missed on PDN 16_0048

Publication Date:	27-Mar-2018			
Last Time Buy Date:	29-Mar-2018			
	00.14 00.40			

Last Time Ship Date: 30-Mar-2018

Revision Description:

Not all FG part numbers from selected HMC generics included in PDN 16_0048

Reason For Discontinuance

Low Demand and other FG part numbers from same generic discontinued in 2016

Comments

Additional obsolete FG part numbers not included in original PDN 16-0048

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representitive						
Americas:	PDN_Americas@analog.com	Europe:	PDN_Europe@analog.com	Japan: Rest of Asia:	PDN_Japan@analog.com PDN_ROA@analog.com	

PDN 18_0011 Discontinued Parts Material List					
Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments	
HMC384LP4	HMC384	HMC384LP4E	Yes	Bulk part missed on original PDN	
HMC388LP4	HMC388	HMC388LP4E	Yes	Bulk part missed on original PDN	
HMC6209LP5E	HMC6209	HMC531LP5E	Yes	Bulk part missed on original PDN	
HMC6630LP5E	HMC6630	HMC511LP5E	Yes	Bulk part missed on original PDN	
HMC7828LP5ETR	HMC7828	HMC8027ALP5ETR	Yes	TR part missed on original PDN	

Appendix A - PDN 18_0011 Revision History						
Rev	Rev Publish Date Rev Description					
Rev	Rev 27-Mar-2018 Not all FG part numbers from selected HMC generics included in PDN 16_0048					
		Analog Devices, Inc. Proprietary Information	Docld:1234	Layout Rev:2	Parent Docld:None	