

Product Change Notification (PCN)

PCN Number 501709 Date Issued January 12, 2017

Reason for Change

Change to Product

Change Type Description

This letter is to inform you that changes are being made to the part(s) identified in this Notice. The change will affect the fit, form, function or appearance of the parts. Or, it may result in a change to the specification. The pictures below show an example of the possible differences.

Reason for Short Notice

Force Majeure

Assessment of Change

Product will be fully qualified before it is shipped. Qualification reports are available upon request.

Internal Molex Qualification Date

January 25, 2017

Sample Availability Date (Changed Part)

January 25, 2017

Planned Implementation Date

January 25, 2017

Method of Identifying Change

Product made after planned implementation date can contain the change

Before Change

 Molex is changing the tin plating on the 2.8mm male and female terminal. Examples shown below.





molex

After Change

Overview

- Molex is changing the tin plating on the 2.8mm male and female terminal due to a change at the plating suppler. Molex's supplier is no longer able to make the current plating. The new plating is an improved version of the existing plating.
- Product Impact
 - There is no negative impact to fit, form or function of the product.
- Part Number Impact
 - 980140100, 980140200, 980140300, 980120102, 980120202, 980120302, 980121102, 9801202 & 980121302
- PPAP and samples available upon request
- © 2018 Molex All Rights Reserved, Unauthorized Reproduction Distribution is Prohibited.

molex



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:501709" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com