## HellermannTyton

3/26/2021

## Subject: Change Notification

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

Type (Only Checked Changes Apply)			
☑ Production/assembly location	$\Box$ N	laterial	$\Box$ End of Life w/ replacement
☑ Part Number/Ordering Code		ackaging	$\Box$ End of Life w/o replacement
⊠ Country of Origin	$\Box$ P	oint of Purchase	□ Additional tool/refurbishment
$\Box$ Design (fit, form, function)	$\Box$ P	oint of Pick up	□ Cost/Lead Time
$\Box$ Engineering record (non-fit, form,	function) $\Box$ S	upply Chain	$\Box$ Process
Additional Information			
From:		To:	
HT Order Code: 126-00036	HT Order Code: 126-00426		
Production Location: Germany	Production Location: Poland		
Country of Origin: Germany	Country of Origin: Poland		
Scope			
HT PN / Ordering Code	<b>Customer PN</b>	(	Change Effective*
126-00036	1436-1741-ND	7	//26/2021

\*Effective date is subject to change based on availability

We ask that you please acknowledge this notification by 4/16/2021, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Dylan Goetzke Quality Project Administrator Office: 414 355 1130 x 8751 Email: <u>dylan.goetzke@htamericas.com</u>