

## Global Change Notification (GCN)

Product Family	.093" Pin and Socket Receptacle	10630957
		GCN Number
Series	1396	March 31, 2014
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	The mold used to make housing 1396-R2/R4 has reached its end of life and is being replaced by an identical tool.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	New Capacity	
Assessment Of Change (How Product Will Be Qualified & Validated)	The new tool will be fully qualified by Molex before it is released to production. The housings produced from the new mold will be identical to the current parts.	
Internal Molex Qualification Date (Planned Date Information Available)	April 03, 2014	
Sample Availability Date (Changed Part)	April 03, 2014	
Date of Implementation	June 03, 2014	
Method of Identifying Change	Product made after June 3, 2014.	
Recommended Replacement Parts	Not Applicable	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

**Molex, Inc.**  
 2222 Wellington Court  
 Lisle, IL 60532  
 TEL: 630-969-4747  
[www.molex.com](http://www.molex.com)