



Product Change Notification (PCN)

PCN Number	510595	Date Issued	July 20, 2021
Reason for Change	Change Supplier		
Change Type Description	This letter is to inform you that Molex is adding a new supplier or the supplier is making a change affecting the part(s) identified in this notice. There will be no negative impact to product performance as a result of this change.		
Reason for Short Notice	Special Request		
Assessment of Change	Test report/Specification Test Report		
Internal Molex Qualification Date	July 16, 2021		
Sample Availability Date (Changed Part)	July 16, 2021		
Planned Implementation Date	August 23, 2021		
Method of Identifying Change	Special marking on the product or packaging		

RELEASED

Before Change

Supplier's material	Raw Material	Molex Products
Current	LCP UL94V-0	503772/505550 series
Alternative	LCP UL94V-0	503772/505550 series

- The severe winter storm that had widespread impacts across the United States, Northern Mexico, and parts of Canada from February 13 to 17, 2021 has caused a global shortage for various grades of resin. This extraordinary event, in conjunction with an already constrained market, has caused immediate and severe disruption in the industry.
- Due to these supply constraints, Molex identified an internal shortage of resin supply with would create a challenge to fulfill all orders. Therefore, we identified an alternative sourcing for the product families listed above. After applying of this change, Molex products listed above will be manufactured by one of them - the current supplier's material or the alternative supplier's one by the resin material supply situation.
- We apologize for the inconvenience, but in view of the urgency of this matter, if there is no particular reply to the change notified by this PCN, it will be considered that the change have been approved and will be implemented with the above Planned implementation Date.
- Part number Impacted.
See the attached impacted parts list.

After Change

- The alternative supplier operates under ISO9001 certified quality management system.
- Molex material scientists conducted comprehensive equivalency analysis comparing properties of resins between the original supplier and alternative supplier. This is being followed by Molex internal qualification testing which shall ensure that finished products meet relevant product specifications before delivery.
- Almost no see shade difference. See the pictures from before and after of this change. Also, there is no expected change regarding form, fit or function.



- Identification:
For the first 6 months of the production start by the alternative material, we will add "M" at the end of Traceability number (see the picture right) of the carton label to identify products made from alternative materials.



Carton label (sample image)



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:510595**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

PCN # Molex Part #

510595 5055501620

510595 5055502420

Part numbers affected:

505550-1020
505550-3020
505550-3420
505550-4020