



Title of Change:	Update to PD22637X – Reactivation of previously discontinued part MMBF4117 and BSR57		
Last Time Buy Date:	NA		
Last Ship Date:	NA		
Contact information:	Contact your local ON Semiconductor Sales Office or <PCN.Support@onsemi.com >		
Type of notification:	ON Semiconductor will consider this change accepted, unless an inquiry is made in writing within 30 days of delivery of this notice.		
<p>Description and Purpose:</p> <p>ON Semiconductor wishes to inform customers of this update to PD22637X - announcing the reactivation of previously discontinued parts MMBF4117 and BSR57 which shall continue production for at least the next 5 years.</p> <p>This update notice is issued upon customer's request.</p> <p>For questions or concerns regarding this notification, please contact your local sales office or customer service representative.</p> <p>Additional contacts are:</p> <table border="0"> <tr> <td style="vertical-align: top;"> <p>Americas:</p> <p>Tom Siegel (tom.siegel@onsemi.com) ☎ +1 765 868 5022 USA</p> <p>Japan:</p> <p>Isao Usuki (isao.usuki@onsemi.com) ☎ +81 3 5817 1060 Japan</p> </td> <td style="vertical-align: top;"> <p>Europe:</p> <p>Andrej Tomasik (andrej.tomasik@onsemi.com) ☎ +421 33790 2229 Slovakia</p> <p>Asia Pacific:</p> <p>Stephen Ng (stephen.ng@onsemi.com) ☎ +852 2689 0209 China</p> </td> </tr> </table>		<p>Americas:</p> <p>Tom Siegel (tom.siegel@onsemi.com) ☎ +1 765 868 5022 USA</p> <p>Japan:</p> <p>Isao Usuki (isao.usuki@onsemi.com) ☎ +81 3 5817 1060 Japan</p>	<p>Europe:</p> <p>Andrej Tomasik (andrej.tomasik@onsemi.com) ☎ +421 33790 2229 Slovakia</p> <p>Asia Pacific:</p> <p>Stephen Ng (stephen.ng@onsemi.com) ☎ +852 2689 0209 China</p>
<p>Americas:</p> <p>Tom Siegel (tom.siegel@onsemi.com) ☎ +1 765 868 5022 USA</p> <p>Japan:</p> <p>Isao Usuki (isao.usuki@onsemi.com) ☎ +81 3 5817 1060 Japan</p>	<p>Europe:</p> <p>Andrej Tomasik (andrej.tomasik@onsemi.com) ☎ +421 33790 2229 Slovakia</p> <p>Asia Pacific:</p> <p>Stephen Ng (stephen.ng@onsemi.com) ☎ +852 2689 0209 China</p>		
<p>List of Affected Standard Parts:</p> <p>Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the <u>PCN Customized Portal</u>.</p> <p>MMBF4117 BSR57</p>			

Appendix A: Changed Products

Product	Customer Part Number	Replacement Parts	Replacement Suppliers
BSR57		NA	NA
MMBF4117		NA	NA