

CUSTOMER OPERATIONS 160 RIO ROBLES SAN JOSE, CA 95134 PDN #: M001032IA

DATE: 28-Dec-2021

PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommeded Replacement | Last Order Date | Last Delivery Date | Reason |
|--------------|-------------------|------------------------|-----------------|--------------------|--|
| Reactivation | MAX40004ANS05+ | N/A | | | Part reactivated from prior notice: M001032I |
| Reactivation | MAX40004ANS05+T | N/A | | | Part reactivated from prior notice: M001032I |
| Reactivation | MAX40004AUK+ | N/A | | | Part reactivated from prior notice: M001032I |
| Reactivation | MAX40004AUK+T | N/A | | | Part reactivated from prior notice: M001032I |
| Reactivation | MAX40004AUK02+ | N/A | | | Part reactivated from prior notice: M001032I |
| Reactivation | MAX40004AUK02+T | N/A | | | Part reactivated from prior notice: M001032I |
| Reactivation | MAX40004AUK05+ | N/A | | | Part reactivated from prior notice: M001032I |
| Reactivation | MAX40004AUK05+T | N/A | | | Part reactivated from prior notice: M001032I |