

Product Change Notification

PCN#: TIES AND TERMINALS - 2018-05-11-Nylon 12 Ties Issue Date: 11May2018

Impacted Regions: NA NEMEA NATAM NAP

Reason for Change: Discontinuation Solution of new mark

DESCRIPTION OF CHANGE: (Not required for discontinuation)

All Nylon 12 cable ties will now have an updated design in a form of an "X" located near the cable tie head. This new mark will help identify that this cable tie as Nylon 12.

PHOTOS/DRAWING (where applicable)



IMPACTED PART NUMBERS AND REPLACEMENT (where applicable) PART NUMBERS

Running Change on the following part numbers: PLT1M-C120, PLT1M-M120, PLT1.5I-C120, PLT1.5I-M120, PLT2S-C120, PLT2S-M120, PLT2.5S-C120, PLT2.5S-M120, PLT3S-M120, PLT4S-C120, PLT4S-M120, PLT4H-TL120, PLT7LH-C120, PLT8LH-C120

DATES DISCONTINUATION AND NEW PRODUCT AVAILABILITY

Schedule for Changes	YEAR (YYYY)	Month (MMM)	Day (DD)
New product sample availability date	2018	05	21
Old product discontinuation date			

^{*}Important: After old product discontinuation date, the affected part numbers listed above will continue to be available for sale as long as supplies last. Product may be returned up to 60 days after the product discontinuation date.

World Headquarters U.S.A. | 18900 Panduit Drive | Tinley Park, IL 60487 | P: 800-777-3300 | www.panduit.com



FORM C2-1003 DATE: 18JUL17 APPR: GKH



FORM C2-1003 DATE: 18JUL17 APPR: GKH