



Product Change Notification

TE Connectivity

Product Change Notification: E-19-009468

PCN Date: 24-JUN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
Insertion tools

Description of Changes
CHANGE MADE TO TREADS THAT INTERFACE WITH THE INSERTION TOOL BODY. FOR ADDITIONAL INFORMATION ABOUT THIS CHANGE AND HOW IT AFFECTS PRODUCT THAT IS IN THE FIELD PLEASE CONTACT THE TE TOOLING ASSISTANCE CENTER AT 800-722-1111 OR fieldservicesnorthamerica@te.com

Reason for Changes:
Product Improvement. THREAD USED ON CURRENT TIPS DID NOT INTERFACE PROPERLY WITH THE BODY OF THE INSERTION TOOL RESULTING IN THE TIP NOT BEING ABLE TO BE THREADED COMPLETELY INTO THE INSERTION TOOL BODY.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	10-JUL-2019
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-1437514-5	NO			"399-HT-113"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-1437514-5	NO			"399-HT-113"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5-1437514-5	NO			"399-HT-113"			