



TE Connectivity

Product Change Notification: P-16-012547 PCN Date: 21-JAN-16

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
62 Position MR Series Connector 211580-2

Description of Changes
The RoHS compliant code in the TE computer databases was changed to indicate 211580-2 is not RoHS compliant.

Reason for Changes:

New specification. The RoHS compliant code was mistakenly changed from not compliant to compliant on Sept 1, 2015. The code was correctly reset to RoHS compliant Jan 21, 2015. No physical changes have been made to the connector.

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Date To Ship (Changed Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Number(s)	Number	Part Number(s)	Difference
211580-2	NO						

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Number(s)	Number	Part Number(s)	Difference
211580-2	NO						

Part Number(s) being Modified:

Part	Part Discontinued	Customer	Customer Part	Alias Part	Substitute Part	Substitute Alias	Description Of
Number	per PCN	Drawing	Number	Number(s)	Number	Part Number(s)	Difference
211580-2	NO						