

PRODUCT CHANGE NOTIFICATION

Product Category FIBER CONNECTORS 20220816-1

Product Group ENTERPRISE CONNECTIVITY

ISSUE DATE: 16-Aug-22

IMPACTED REGIONS: NA EMEA LATAM AP

REASON FOR CHANGE: DISCONTINUATION
 OTHER

DESCRIPTION OF CHANGE: (Required)

The increasing trend towards fusion-splice and OptiCam connectors means the field-polish solution is being simplified. The FIELDKIT termination kit and FIELDKITRFB replenishment kits will continue to be sold to support FLCSSBUY, FLCSEMBLY, and FSCM5BL field-polish connectors. All other field polish connectors & consumables are being discontinued. Customers are encouraged to become familiar with these fusion-splice and/or OptiCam connectors & select the option that best supports project needs.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2022	11	14

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit’s Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)

FKITCASE

FCLEANKIT